

# PREROUNDER DIES

## 5 and 13 ton tools Selection table for Cu-dies

| Cross section mm <sup>2</sup> | For compression tools 5-6 ton | El. no.   | For compression tools 13 ton | Art. no. |
|-------------------------------|-------------------------------|-----------|------------------------------|----------|
| 25                            | UP5,1-50                      | -         | UP130-25                     | 99 35 05 |
| 35                            | UP6,3-50                      | 20 205 71 | UP130-35                     | 99 35 06 |
| 50                            | UP7,5-50                      | 20 205 72 | UP130-50                     | 99 35 07 |
| 70                            | UP9,0-50                      | 20 205 73 | UP130-70                     | 99 35 08 |
| 95                            | UP10,5-50                     | 20 205 74 | UP130-95                     | 99 35 09 |
| 120                           | UP12,5-50                     | 20 205 75 | UP130-120                    | 99 35 10 |
| 150                           | UP14,0-50                     | 20 205 76 | UP130-150                    | 99 35 11 |
| 185                           | UP15,7-50                     | 20 205 77 | UP130-185                    | 99 35 12 |
| 240                           | UP17,5-50                     | -         | UP130-240                    | 99 35 13 |

